

EQUITY MINE

PO Box 1450 Houston, British Columbia Canada V0J 1Z0

Mike Aziz Manager **TEL** (250) 845-7799 **FAX** (250) 845-2137 mike.aziz@goldcorp.com

June 30, 2015

Al Hoffman, Chief Inspector of Mines Victoria, BC

Re: 2015 Response Letter for Equity Silver Mine

Under cover of this letter, please find a response letter written by Amec Foster Wheeler Environment & Infrastructure responding to the Ministerial Order of February 3, 2015 for the Equity Silver mine.

Goldcorp Canada Ltd. is committed to ensuring the safe operation of all tailings facilities and dam structures under our control. The Amec letter identifies some additional work required:

- Drilling into foundations of the tailings dams to validate the previous geological models and update the stability assessments for the three dams.
- Updated seepage analysis to be completed for evaluating the gradients at the till/rockfill interface of the Diversion dam starter dam given the changing water levels in the Diversion Pond.

Goldcorp Canada Ltd. is planning to complete the additional work this year, but the drilling work will be dependent on the proper drill rig being available prior to snowfall next fall.

Please do not hesitate to contact me if you have any further questions regarding the operation, maintenance and monitoring of our tailings facility.

Sincerely,

Mike Aziz Mine Manager

mile Och