



Bralorne Gold Mines Ltd.  
General Delivery  
Gold Bridge, BC  
V0K 1P0

Mr. Al Hoffman,  
Chief Inspector of Mines  
Ministry of Energy, Mines and Natural Gas  
Health and Safety and Permitting Branch  
PO Box 9320 STN Prov Govt  
Victoria BC V8W 9E2

June 30, 2015

**Re: 2015 Letter of Assurance for Bralorne Gold Mines Ltd.**

Under cover of this letter, please find a report was prepared by Tetra Tech EBA Inc., consulting geotechnical engineers. Tetra Tech EBA has addressed the assessments outlined in items 1, 2 and 3 of your memorandum dated February 3, 2015.

As outlined in the report by Tetra-Tech, there is no evidence currently available to indicate the presence of weak layers in the embankment foundation of the Bralorne tailings storage facility (TSF). The filter criteria within the embankment were determined to meet current standards and guidelines. The current TSF is not adequate with respect to water balance; however, the planned raise of the tailings embankment will increase both tailings storage capacity and the buffer capacity for design storms and surplus water. Bralorne has also commenced planning with respect to alternative management of underground mine water.

To confirm the previous findings and provide further data points, BGM is planning to collect geotechnical data during the installation of new piezometers as part of the dam raise program planned for 2015. BGM plans to replace existing standpipe piezometers installed in the TSF embankment in 2015 and will confirm the ground conditions at select locations below the embankment at that time.

Bralorne is striving to meet the highest standards of safety for our tailings facility including all of the guidance provided by the Canadian Dam Association. We intend to adapt our tailings management system to follow industry best practices and will make an effort over time to adopt the "Towards Sustainable Mining" initiative of the Mining Association of Canada. Bralorne does not have an Independent Tailings Dam Review Board (ITRB) in place. This will be considered as we move forward following the tailings dam raise, which is scheduled in the coming months.

Please do not hesitate to contact me if you have any further questions regarding the operation, maintenance and monitoring of our tailings facility.

Sincerely,

Lee Heichert  
Mine Manager  
Bralorne Gold Mines Ltd.