

# Ministry of Energy and Mines

Mines and Mineral Resources Division

**MEMORANDUM** 

Date: January 27, 2015

To: Dallas Rodier, Mine Manager Brenda – Glencore Canada

[Sent by Email: dallas.rodier@glencore-ca.com]

Cc: Diane Howe, Deputy Chief Inspector, Reclamation and Permitting, MEM

George Warnock, Manager, Geotechnical Engineering, MEM

Heather Narynski, Sr. Geotechnical Inspector, MEM

## Re: Review of Submission in Response to Chief Inspector's Orders Issued on August 18, 2014

The Ministry of Energy and Mines has engaged a consulting firm to ensure the consistency and compliance of your submissions in response to the Chief Inspector's orders issued on August 18, 2014. This high-level review has determined that your submission is <u>incomplete</u>. The Ministry recognizes receipt of all documents, as requested; however, a dated Dam Break Inundation Study was received. In addition, the following items shall be addressed:

#### Dam Safety Inspection (DSI) Report:

 For consistency with APEGBC's Quality Management Guidelines: Use of the APEGBC Seal and good engineering practice, you are reminded that the DSI is to be signed and sealed by an APEGBC P.Eng.

### Third Party Review (TPR) of Dam Safety Inspection Report:

• For consistency with APEGBC's *Quality Management Guidelines: Use of the APEGBC Seal* and good engineering practice, you are reminded that the TPR is to be signed and sealed by an APEGBC P.Eng.

## Emergency Preparedness and Response Plan (EPRP):

- For consistency with CDA Guidelines and good engineering practice, the next revision of the EPRP shall include the following, and be resubmitted by June 30, 2015:
  - The EPRP shall be revised when the new Dam Break Inundation Study is complete, and incorporate results of the DBI as well as result of the EPRP test.
  - Roles and responsibilities of the Emergency Operations Centre (CDA Guidelines, Sections
    4.3 and 4.5)

## Dam Break Inundation (DBI) Study:

 The submitted DBI predates the CDA Guidelines and also may not address all existing downstream infrastructure. For consistency with CDA Guidelines and good engineering practice, the DBI shall be updated. The updated DBI shall be signed and sealed by and APEGBC P.Eng. The revised DBI shall include the following items and be re-submitted by June 30, 2015:

- o Inundation-map for sunny-day and flood-induced, overtopping and piping failures
- o Tailings Runout Assessment

In addition to the requirements listed above, all recommendations made by your consultants within each document submitted shall be addressed in the timeframe specified. MEM will be following-up in the fall of 2015 to obtain a status update with respect to all recommendations and commitments, as well as any submission deficiencies as noted above.

This review is specific to the orders issued on August 18, 2014, which does not encompass all aspects of dam safety relating to the tailings dam(s). Please ensure that you are meeting your ongoing requirements with respect to the following:

- Satisfying any outstanding orders from previous Ministry's inspection reports.
- Satisfying any outstanding recommendations from previous Dam Safety Inspections (DSI) or Dam Safety Reviews (DSR).
- Submission of annual Dam Safety Inspection (DSI) reports as per Section 10.5.3 of the Health, Safety and Reclamation Code for Mines in BC (Code). These reports are to be submitted by March 31<sup>st</sup> in the year following the inspection. The next DSI (for 2015) will be due March 31, 2016.
- Submission of Dam Safety Review (DSR) reports based on the dam consequence classification frequency as outlined in the Canadian Dam Association (CDA), 2007 Dam Safety Guidelines. The DSR shall follow APEGBC's "Professional Practice Guidelines for Legislated Dam Safety Reviews in BC". This document can be located at: <a href="http://www.empr.gov.bc.ca/MINING/PERMITTING-RECLAMATION/GEOTECH/Pages/default.aspx">http://www.empr.gov.bc.ca/MINING/PERMITTING-RECLAMATION/GEOTECH/Pages/default.aspx</a>, or on the APEGBC website.
- A current Operation, Maintenance and Surveillance (OMS) manual which shall be regularly revised during operations, decommissioning and closure as per Section 10.5.2 of the Code.
- A current Emergency Preparedness and Response Plan (EPRP) and Dam Break Inundation Study which shall be regularly revised (applies to "high", "very high" and "extreme" consequence dams).
- Submission of as-built reports subsequent to new construction and any dam raise as per Section 10.5.1 of the Code.
- Submission of closure plans, and installation of a spillway, designed by a Professional Engineer, in accordance with the CDA, Dam Safety Guidelines prior to closure as per Sections 10.6.10 and 10.7.19 of the Code, respectively.

I remind you of your responsibility to ensure full compliance with orders, permit conditions and the requirements of the *Mines Act* and Health, Safety and Reclamation Code at all times. It is my expectation that the information requested will be submitted in the timeframe provided.

I look forward to your diligent and timely attention to this matter.

Sincerely,

Al Hoffman, P. Eng. Chief Inspector of Mines Ministry of Energy and Mines